Toni Harvey (Oil & Gas Authority)

From: lan Gray El <ian.gray@surreycc.gov.uk>

Sent: 26 July 2018 18:31

To: Toni Harvey (Oil & Gas Authority)

Cc: Stephen Jenkins El; Samantha Murphy El; Caroline Smith El; Mike Green El

Subject: Seismic activity in Surrey, the BGS and quarry sites in Surrey

Hi Toni,

Further to our discussion in respect of the British Geological Society struggling to explain the recent seismic activity in the Brockham/Gatwick area, I recalled that I can bring up mineral sites on our GIS mapping system.

The mineral sites are shown in pale yellow on the maps below:

Map 1/.

Lilac circle:

This has Brockham oil well site as it's centre with a 5km radius.

Red Triangle:

Brockham well located at western end of the triangle, Buckland Sand Pit (silica sand extraction completed and restored to lakes with no infill), at the eastern point and Betchworth Quarry landfill (an old chalk quarry which took domestic waste and is unlined), at the northern point. Below the red circle, to left of the word Buckland, in another pale yellow rectangle, which represents Reigate Road Sand Pit, which is still in active mineral extraction with inert infill.

Map 1/.

Lilac circle:

This has Horse Hill well site as it's centre with a 5km radius.


Red Triangle:

Horse Hill located directly above Hookwood at the bottom right of the triangle, to the north is Buckland Sand Pit (to tie in to the other map), at Leigh is the Bury Hill exploration site, and at Beare Green is South Holmwood, with Capel Brickworks further to the southwest at Capel. Both of the brickworks traditionally undertake clay lifts in spring and autumn to provide a large working stockpile for the next six months. Volumes will depend upon t demand of course. On the western edge of the map you can see another pale yellow area at (Wa)lliswood, where Smokejacks is sited, yet another clay quarry and brickworks.


I will ask someone in our Highways Department whether they are aware of any old bridges that are due for repair and may be known to be leaking water as a result of structural damage.

I hope this helps a little.

Map 1/.



Map 2/.



Regards, Ian

Ian Gray - Team Leader Planning Enforcement

Highways, Transport & Environment Surrey County Council

Contact details:

Phone: 020 8541 9423

Email: Ian.Gray@surreycc.gov.uk

This email and any attachments with it are intended for the addressee only. It may be confidential and may be the subject of legal and/or professional privilege.

If you have received this email in error please notify the sender or postmaster@surreycc.gov.uk

The content may be personal or contain personal opinions and cannot be taken as an expression of the County Council's position. Surrey County Council reserves the right to monitor all incoming and outgoing mail. Whilst every care has been taken to check this e-mail for viruses, it is your responsibility to carry out any checks upon receipt.

Visit the Surrey County Council website - http://www.surreycc.gov.uk